



Change List for Win7 Driver 8.0.0.144 to 8.0.0.171

Draft July/16/2009

Atheros is continuing Hot Fixes. This will be a list of running changes as we continue to fix defects against Win7 8.0.0.x base code.

Software changes between build 8.0.0.144 and 8.0.0.162 (SID:1335625)

- 1) Add generic INF entries.
- 2) Prepare driver to support HB97/MB97. It is currently not officially supported.
- 3) Added Win7 and Server 2008 INF support.
- 4) Fixed synchronization issue between ndisPauseMiniport and the OIDs processing.
- 5) Incremented the reference count of the node used by scan to transmit probe requests.
- 6) Fixed HB93 can't connect by Adhoc after driver disable/enable.
- 7) Fixed Background scan interrupts data transfer via IEEE1394. Enable registry analogShiftRegDelay to add delay after writes to analog shift registers.
- 8) Fixed BSOD when AP disassociate clients.
- 9) Fixed Cisco AP's TPC causes low throughput with XB62. Add a registry key to specify the lowest tx power we can support.
- 10) Report SoftAP's current PhyId in association completion indication.
- 11) Limit the duration of a single roaming attempt to 20 seconds.
- 12) Take VAP out of RUN state when SW beacon miss is detected.
- 13) Fixed driver shows legacy link speed with 11n AP.
- 14) Fixed HB95 causing high CPU utilization while Radio-off.
- 15) Fixed driver is deleting a lock that is still owned by a thread.
- 16) Fixed problem causing scan to try to transmit fake sleep and fake wake up even if client is not connected.
- 17) Fixed problem causing scan to visit first foreign channel even in the presence of traffic.
- 18) Added a new OID and supporting interfaces to get chain specific noise floor values.

Software changes between build 8.0.0.162 and 8.0.0.171 (SID:1338646)

- 19) Add generic INF entries.
- 20) Fixed Driver is indicating receive NBLs at passive level with NDIS_RECEIVE_FLAGS_DISPATCH_LEVEL set.
- 21) Fixed problem causing scan entries never to be aged out if AP is restarted with different SSID.
- 22) Fixed cleaning up RFKill polling when power state set to D3.
- 23) Fixed 9F Bugcheck caused by timer cancellation not handled properly.
- 24) Fixed Driver fails to free its pool allocations prior to unloading.
- 25) Fixed HB95 has low throughput with Cisco1250.
- 26) Fixed scan list shows APs with channel 14 though SKU disables ch 14.
- 27) Fixed completing all tx packets when radio disabled by hardware RFKill.



Change List for Win7 Driver 8.0.0.144 to 8.0.0.171

Draft July/16/2009

- 28) Fixed incorrect link speed in "Wireless Network Connection Status" when
 cwmMode = 0.
- 29) Fixed BSOD Once Switching to Turbo.