



Intel® Turbo Boost Technology Driver

Release Notes

November 2009

Revision 1.0.1.1002

Introduction



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. UNLESS OTHERWISE AGREED IN WRITING BY INTEL, THE INTEL PRODUCTS ARE NOT DESIGNED NOR INTENDED FOR ANY APPLICATION IN WHICH THE FAILURE OF THE INTEL PRODUCT COULD CREATE A SITUATION WHERE PERSONAL INJURY OR DEATH MAY OCCUR.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or by visiting [Intel's Web Site](#).

Intel and the Intel logo are trademarks of Intel Corporation or its subsidiaries in the U.S. and other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2009 Intel Corporation. All rights reserved.



Contents

1	Introduction.....	5
1.1	Supported Operating Systems	5
1.2	Supported Intel® Integrated Graphics Driver [IGD].....	5
1.3	Supported Intel® Turbo Boost Technology Installation Configurations.....	5
2	Feature Set	6
3	Issues – Fixed in this release	7
4	Issues – Fixed in previous releases	8
5	Issues – Known in this release	9

Tables

Table 1	Installation Combinations.....	5
Table 2	Feature Set.....	6
Table 3	All Issues fixed in the 1.0.1.1002 PV Release.....	7
Table 4	All Issues fixed in the 1.0.0.1030 PV Release.....	8
Table 5	Known Issues in the 1.0.1.1002 PV Release.....	9



Revision History

Package Definition	Intel® Intelligent Power Sharing Driver Revision	Release Date
1.0.1 PV	1.0.1.1002	November 6, 2009
1.0 PV	1.0.0.1030	October 20, 2009



1 Introduction

1.1 Supported Operating Systems

- Microsoft Windows 7* x32 Edition (RTM Build 7600)
- Microsoft Windows 7* x64 Edition (RTM Build 7600)
- Microsoft Windows Vista* x32 Edition (Ultimate SP2)
- Microsoft Windows Vista* x64 Edition (Ultimate SP2)
- Microsoft Windows XP* x32 Edition (Professional SP3)
- Microsoft Windows XP* x64 Edition (Professional SP2)

Basic Acceptance Tests (BAT) was performed on all the above mentioned Operating Systems. The Platform and Functional tests were performed on Microsoft Windows Vista* x32, Microsoft Windows Vista* x64 and Microsoft Windows XP* x32 Editions. Stress tests were performed on Microsoft Windows Vista* x64 and Microsoft Windows XP* x32 Editions. Some of the stress tests were also performed on Microsoft Windows Vista* x32 Edition.

1.2 Supported Intel® Integrated Graphics Driver [IGD]

- For Microsoft Windows Vista*, please use IGD version 15.16.1968 or later
- For Microsoft Windows XP*, please use IGD version 14.41.5148 or later
- For Microsoft Windows 7*, please use IGD version 15.16.1968 or later.

1.3 Supported Intel® Turbo Boost Technology Installation Configurations

Table 1 Installation Combinations

Installer	Integrated Graphics SKU	Discrete Graphics SKU	Switchable Graphics SKU
Independent	NO	YES	YES
Combined	YES	NO	NO



2 Feature Set

Table 2 Feature Set

Feature	Description
32-bit OS support	Support for Microsoft® Windows Vista x32 Edition (SP2), XP, and Windows 7.
64-bit OS support	Support for Microsoft® Windows Vista x64 Edition (SP2), XP, and Windows 7.



3 *Issues – Fixed in this release*

Table 3 All Issues fixed in the 1.0.1.1002 PV Release

Reference No:	Description
N/A	Please see Intel® Integrated Graphics Driver Release Notes for a description of the supported driver fixes.
3289904	Turbo status not restored after S-state testing occasionally
3290257	GFX Turbo is improperly disabled with CPU reporting feature stopping

* Other names and brands may be claimed as the property of others.



4 *Issues – Fixed in previous releases*

Table 4 All Issues fixed in the 1.0.0.1030 PV Release

Reference No:	Description
N/A	Please see Intel® Integrated Graphics Driver Release Notes for a description of the supported driver fixes.
3175833	Turbo Boost driver reports CPU Turbo status as on when disabled in BIOS when configured EC through SMBUS
3177288	Turbo Boost driver changes processor temperature limit back to default
3177300	Instantaneous GMCH power exceeds GMCH platform limit
3177315	Instant CPU power exceeds CPU platform limit
3290143	OS hangs coming out of S3 when AC power is introduced
3290293	System hang during S3 cycles when USB Controller changes



5 Issues – Known in this release

Table 5 Known Issues in the 1.0.1.1002 PV Release

Reference No:	Description
N/A	Mixed use of the standalone Intel Turbo Boost Technology Driver and combined Intel Integrated Graphics and Intel Turbo Boost Technology driver kits is not functioning. Only one installer or the other can be used at a time. A clean install will be required when switching between installer packages.

§