



## Release Notes for SH100S3, Firmware Rev. 501 (03/06/12)

- Enhanced reliability during power cycles and secure erases
- Resolved a unique issue that would block a TRIM command sent by an application while in IDE mode using Windows XP or Windows 7
- Enhanced TRIM throughput
- Improved write performance